

dry stone walls. Many of the walls are totally collapsed and are overgrown with grass and trees. A line of stones, some walls are standing in its northern side which is where the old palisade fence is situated (site 7). The west and southern most walls also act as retaining walls on their east and northern sides respectively.

SITUATED: February 18/3/95.


DESCRIPTION

Dry Stone Building - Partially to totally collapsed dry stone building rectangular in shape. 274m x 5.7m situated in an enclosure. Site 9 - consisting of 4 forms of stone. Northern floors only 2 entrances are visible, both in the southern wall. One entrance is in the western most room, the other is in the 2nd room from the eastern end. The wall is 2 rooms are collapsed and overgrown with grass and an entrance cannot be distinguished. The northern most wall is collapsed and overgrown with grass. The stone walls are situated standing on and in the eastern dividing wall of the eastern most room. There is situated standing on and in the eastern dividing wall of the eastern most room.

Wall 1: A dry stone wall attached to the building, 3.4m x 0.6m with a larger area of 7.5m x 0.6m.

Wall 2: Partially collapsed dry stone wall. Part of the wall acts as a retaining wall in some places.

Wall 3: A line of stones partially overgrown with grass, possible dry stone wall.



DESCRIPTION

The site settlement is situated on the northern side of the A82 road, east of Achtrachatan. It consists of the ruins and foundations of a number of dry stone buildings, structures, enclosures and walls. The settlement is situated adjoining the southern edge of the old military road. Most walls are collapsed or partially collapsed and overgrown with grass or covered with earth. The vegetation in the area is grass and five large trees.

It is reported that there was a landslide at one time which demolished the site. At the moment however, there is little evidence to support this.

SURVEYED


D.W. 22/4/95. F. Henry 3/5/95.

DESCRIPTION

A series of small earthen walls running in a north-west direction down the length of the A82 for a distance of 340m until it reaches the boundary of the survey site (The road continues on survey east of 1457). The ruins are situated on the north side of the A82 on a hillside which slopes down north to south. The ruins are cut 51m from the length of the A82 by an 15m wide ditch. The road width is 31m. A drainage ditch runs most of the length of the northern side of the road. A dry stone wall runs parallel to the road on its northern side. This wall is situated 3m from the road edge and acts as a retaining wall in most places. Two large stones in high marks the eastern end of the wall and indicate a possible entrance to the settlement of sites 8, 9 and 10. Six spoil excavation ditches are situated adjoining the southern edge of the road opposite the settlement and 145m from the A82 road. The spoil excavation ditches vary in size from 3m x 4m to 5.2m x 3.7m.


1557

(VIEWED OF SITE 7, SITE 8, SITE 9 and SITE 10) OLD SETTLEMENT



1557 SITE 7: OLD MILITARY ROAD, FIVE SPOIL EXCAVATIONS, AND ONE DRY STONE WALL

1557 SITE 7



REVIEWED: F. Henry 3/5/95

A82 Roadway