

**Photographic Record****Blackhills Steading, Auldearn, Nairn****Ref: 06/000186/OUTNA****Ref: 13/000811/MSC**

<b><u>Photograph No.</u></b>	<b><u>Building</u></b>	<b><u>Location</u></b>	<b><u>Description</u></b>	<b><u>Time</u></b>	<b><u>Date</u></b>
Photograph 1	General	External	Looking west showing north-west elevation of steading.	09.52am	25/03/2015
Photograph 2	General	External	Looking east showing the north-west elevation.	09.57am	25/03/2015
Photograph 3	General	External	Looking north showing the south-west and south-east elevations.	10.01am	25/03/2015
Photograph 4	General	External	Looking north showing the south-east elevation including Building 1 (Dutch barn).	10.01am	25/03/2015
Photograph 5	General	External	Looking north-west showing the south-east and north-east elevations.	10.02am	25/03/2015
Photograph 6	General	External	Looking west showing the north-east elevations including Building 1 (Dutch barn).	10.02am	25/03/2015
Photograph 7	Building 1	External	North-west elevation.	09.53am	25/03/2015
Photograph 8	Building 1	External	North-east elevation.	10.03am	25/03/2015
Photograph 9	Building 1, 6 & 11	External	South-east gable of Building 1, north-east gable of Buildings 6 & 11.	10.03am	25/03/2015
Photograph 10	Building 1 & 2	External	Internal photo of Building 1 and north-east elevation of Building 2.	10.03am	25/03/2015
Photograph 11	Building 2	External	North-west elevation.	09.53am	25/03/2015
Photograph 12	Building 2	External	North-west elevation.	09.53am	25/03/2015
Photograph 13	Building 2	External	North-west elevatons.	09.53am	25/03/2015
Photograph 14	Building 2	External	North-east elevation.	09.55am	25/03/2015

Photograph 15	Buildings 3,4,5,6 & 7	External	Looking south.	09.57am	25/03/2015
Photograph 16	Buildings 3,4,5, & 6	External	Looking south towards the gables of Buildings 3,4 & 5 and part of the north-west elevation of building 6.	09.54am	25/03/2015
Photograph 17	Building 4	External	South-west gable.	09.55am	25/03/2015
Photograph 18	Building 5	External	South-west gable.	09.55am	25/03/2015
Photograph 19	Building 6	External	Visible section of north-west elevation.	09.55am	25/03/2015
Photograph 20	Building 7	External	North-east elevation with door. Please note damage to elevation currently being propped up. No internal photos	09.56am	25/03/2015
Photograph 21	Building 8	External	North-east elevation.	09.56am	25/03/2015
Photograph 22	Building 9	External	Looking north showing the north-east elevation.	09.56am	25/03/2015
Photograph 23	Building 9	External	Looking south showing the north-east elevation.	09.57am	25/03/2015
Photograph 24	Buildings 3,8, 9 & 10	External	Looking south-west towards the north-east elevations of Buildings 8 & 9.	09.57am	25/03/2015
Photograph 25	Building 10	External	North-east elevation.	09.57am	25/03/2015
Photograph 26	Buildings 3-10	External	Looking south-east towards the gable end of Building 9 and elevations of Buildings 3-8.	09.58am	25/03/2015
Photograph 27	Building 10	External	South-west elevation.	09.58am	25/03/2015
Photograph 28	Buildings 7-10	External	Looking north-east towards the south-west elevations of Buildings 7-10.	09.59am	25/03/2015
Photograph 29	Buildings 7-9	External	Looking north-east towards the south-west elevations of Buildings 7-9.	09.58am	25/03/2015
Photograph 30	Buildings 8-9	External	Detail along the south-west elevations of Buildings 8-9.	09.59am	25/03/2015

Photograph 31	Buildings 8-9	External	Detail along the south-west elevations of Buildings 8-9.	09.59am	25/03/2015
Photograph 32	Buildings 8-9	External	Detail along the south-west elevations of Buildings 8-9.	09.59am	25/03/2015
Photograph 33	Building 7	External	South-west elevation.	09.59am	25/03/2015
Photograph 34	Building 7	External	South-west elevation.	10.00am	25/03/2015
Photograph 35	Buildings 6 & 7	External	South-east elevation.	10.04am	25/03/2015
Photograph 36	Buildings 6 & 7	External	South-east elevation.	10.04am	25/03/2015
Photograph 37	Buildings 6, 7 & 11	External	South-east elevation with Building 11.	10.04am	25/03/2015
Photograph 38	Buildings 6, 7 & 11	External	South-east elevation with Building 11.	10.03am	25/03/2015
Photograph 39	Building 2	Internal	Looking south east into Building 2.	10.07am	25/03/2015
Photograph 40	Building 2	Internal	Looking north-west into Building 2.	10.06am	25/03/2015
Photograph 41	Building 2	Internal	View of the roof.	10.07am	25/03/2015
Photograph 42	Building 2	Internal	Looking south-west towards Buildings 3, 4 & 5.	10.07am	25/03/2015
Photograph 43	Building 3	Internal	Looking north-east towards Building 2.	10.07am	25/03/2015
Photograph 44	Building 3	Internal	View of the roof.	10.07am	25/03/2015
Photograph 45	Building 3	Internal	North-east elevation.	10.08am	25/03/2015
Photograph 46	Building 4	Internal	Looking north-east towards Building 2.	10.08am	25/03/2015

Photograph 47	Building 4	Internal	Looking south-west.	10.08am	25/03/2015
Photograph 48	Building 4	Internal	View of the roof.	10.08am	25/03/2015
Photograph 49	Building 5	Internal	Looking north-east towards Building 2.	10.09am	25/03/2015
Photograph 50	Building 8	Internal	Looking south into Building 8.	10.09am	25/03/2015
Photograph 51	Building 8	Internal	Looking north into Building 8.	10.09am	25/03/2015
Photograph 52	Building 9	Internal	Looking north-west into Building 9.	10.10am	25/03/2015
Photograph 53	Building 10	Internal	Looking south-west into Building 10.	10.11am	25/03/2015
Photograph 54	Building 10	Internal	Looking west into Building 10.	10.11am	25/03/2015
Photograph 55	Building 10	Internal	Looking west into Building 10.	10.11am	25/03/2015
Photograph 56	Building 6	Internal	Looking south-west towards Building 7.	10.05am	25/03/2015
Photograph 57	Building 6	Internal	Looking south-west towards Building 7.	10.06am	25/03/2015
Photograph 58	Building 6	Internal	North-west elevation with door leading into Building 2.	10.06am	25/03/2015
Photograph 59	Building 6	Internal	North-west elevation.	10.06am	25/03/2015
Photograph 60	Building 6	Internal	View of the roof.	10.05am	25/03/2015
Photograph 61	Building 11	Internal	Looking south-west into Building 11.	10.05am	25/03/2015